

Laboratory			Al Bader		LABTECH		PROMPT	
No	Calibration field	Calibration item	Range	CMC	Range	CMC	Range	CMC
02	Pressure	Pneumatic pressure gauge			0 to 10000 psi /1psi	0.41%	-1 bar to 120 bar	0.57% FS
		Vacuumed gauge	-1 to 2 bar /0.005 bar	0.07% FS			-1 bar to 200 bar	0.57% FS
		Hydraulic pressure gauge	0 to 70 bar/0.05 bar	0.1% FS	0 to 10000 psi /1psi	0.41%	0 bar to 140 bar 140 bar to 1200 bar	0.39% FS
			0 to 700 bar/0.05 bar 0 bar to 2500 bar/0.1bar	0.36% FS 0.12% FS				
03	Force	Compression machines	Up to 3336 kN	0.66%	0 to 100 kN /0.01kN 0 to 3000 kN /0.01 kN	0.12 % 0.07 %		
		Proving rings			0 to 50 kN /0.01 kN	0.25 %		
		Tension load cell						
		Tension machines						

Evrakın elektronik imzalı suretine <http://e-belge.gtb.gov.tr> adresinden 23898c5e-6541-4ee6-88e3-387b2481595c kodu ile eri ebilirsiniz.
BELGEN N ASLI ELEKTRON K MZALIDIR.